Work	Order ID	59296
Monday,	May 31, 2010	12:38:24 F
I40 ID.	D2922	2

Packaging

Packaging



Page 1

Monday, May 3	1, 2010 12:38:2	24 PM									
Item ID: Revision ID: \ Item Name:	D3832-3 Mesh (Lid)			Accept					Setup Sta		
Start Date: Required Date: Reference:		Start Qty: 3.00 Req'd Qty: 3.00	18 489 144 184 18 488 144 184		Cust Item I Customer:	D:				1100111041	
Approvals:	Process Plan:	:	Date: 10-3-8) Date:	Tooling: SPC (Y/N):		ıte:]	Run Sta Sto		
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr D3832	Revisi Rev A	ion Nbr									
100 	S	SHEAR Memo 1- mesh	to size as per dwg D3832	0.00 0.00 SA	D 10-08	5-0Z	_	3			
110 QC Quality Control	(QC5- Inspect part com Memo	pleteness to step on W/O	0.00 S w	6/02						· <u></u> -
120	Į.	dentify as per dwg & S	Stock Location: WA	0.00 SAW	0 10-06-1	3 2		3			

0.00

Memo

W/O:	,		W	ORK ORDER CHANG	GES				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
		solution:							
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC			tion B	Verifi	cation	Approval	Approval
	J.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	tion C	Chief Eng	QC Inspector
		· · · · · · · · · · · · · · · · · · ·							
·									

Work Ord Monday, May 3												Page 2
Item ID: Revision ID: Item Name:	D3832-3 Mesh (Lid)	·		Accept					Setup	Start Stop	1 18811181 81	
Start Date: Required Date Reference:	5/31/2010	Start Qty: 3.00 Req'd Qty: 3.00			Cust Item I Customer:	D:						······································
Approvals:	Process Pl		Date:	Tooling: SPC (Y/N):		ite:			Run	Start Stop		
Sequence ID/ Work Center I 130 QC Quality Control	D	Operation Description QC21- Final Inspection - Memo	Work Order Release	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accep Qty	Ot Rej Qty	10 l	Reject Number	Insp. Stamp

W/O:			WORK ORDER CHANGES										
DATE			OCEDURE CHAI			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
									; ; ;				
				· · · · · · · · · · · · · · · · · · ·					1170-110				
				•									
Part No		PAR #:	Fault Cate	jory:	_ NCR:	Yes N	lo DQ /	A:	Date:				
•	Res	olution:	Disposition	l:	QA: N	C Clo	sed:		Date:	·			
NCR:			WORK ORDE	R NON-CONFORM	ANCE (I	VCR)							
DATE	STEP	Description of NC Section A	Initial	Action Description		ign &	Verific Section		Approval Chief Eng	Approval QC Inspector			
			Chief Eng	Chief Eng		Date	00011		5s. 2.ng	QO MOPOOLO			
•													
		•											
		·			·	==:							
							i i						
,										s.			

Picklist Print

Monday, May 31, 2010 12:38:30 PM

Work Order ID: 59296

Parent Item:

D3832-3

Parent Item Name:

Comments:

Mesh (Lid)

IPP Rev:A 08-12-01 new issue DD verified by:EC



Start Date: 5/31/2010

Required Date: 6/4/2010

Page 1

Start Qty: 3.00

Required Qty: 3.00


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304EX0.75-16F	_	Purchased	No	-		100	sf	517.9273	11.9367	37.69484			
										<i>a</i>		, «s	

Expanded Metal Flat SS

Location Loc Qty Loc Code MAT 517.9273368 113555 3.6842E-05 114399 108.1523 114594 89.775 114744 320

SAD 10-06-62

•									
		WC	ORK ORDER CHANG	GES					· · · · · · · · · · · · · · · · · · ·
STEP	PRO	OCEDURE CHA	•		Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			1						
								<u>Jan.</u>	
Reso	olution:	Dispositio	n:	QA: N	/C Clo	sed:		Date:	
		WORK ORD	ER NON-CONFORM	ANCE (NCR))			
STEP	Description of NC				····· 0	Verific	ation	Approval	Approval
	Section A	Chief Eng	Action Description Chief Eng			Secti	on C	Chief Eng	QC Inspector
			4						
	•								
		:PAR #:	STEP PROCEDURE CHA PAR #: Fault Cate Resolution: Disposition WORK ORD STEP Description of NC Section A	STEP PROCEDURE CHANGE PAR #: Fault Category: Resolution: Disposition: WORK ORDER NON-CONFORM STEP Description of NC Section A Corrective Action Section A Corrective Action Description	PAR #: Fault Category: NCR: Resolution: Disposition: QA: N WORK ORDER NON-CONFORMANCE (Initial Action Description Section B	STEP PROCEDURE CHANGE By PROCEDURE CHANGE By Fault Category: NCR: Yes If Disposition: QA: N/C Clo WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Corrective Action Section B Initial Action Description Sign &	STEP PROCEDURE CHANGE By Date PAR #: Fault Category: NCR: Yes No DQ/ Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A	STEP PROCEDURE CHANGE By Date Qty PAR #: Fault Category: NCR: Yes No DQA: Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr :PAR #:Fault Category:NCR: Yes No DQA:Date: Resolution:Disposition:QA: N/C Closed:Date: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Section B Section C Secti



W/O:			WO	RK ORDER CH	IANGES				
DATE	STEP	PR	OCEDURE CHAN	NGE	1	Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Dort No.	_	D4D #		·					
Part No		PAR #:							
NOD	Re	esolution:		R NON-CONFO				Date: _	
NCR:			· · · · · · · · · · · · · · · · · · ·			E (NCH	()		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Descrip Chief Eng		Sign &	Verification Section C	Approval Chief Eng	Approval QC Inspector


38.38 W/0 59294 **D3832-1 MESH (BASE)** DART AEROSPACE LTD
HAWKESBURY, ONTARIO, CANADA
DRAWING NO.
D3832
TITLE DESIGN DRAWN CHECKED REV. A MFG. APPR. SHEET 2 OF 3 TITLE APPROVED SCALE MESH (LID) SCAL

OPPRIGHT 0 2008 BY DART AEROSPACE LTD

THIS COLOMBRIT 0 SWALL HOLD COMPOSED ALL SHOPE, OF THE CONTROL THAT ITS

BOT TO BE USED FOR MAY PLANCED ALL OFFICE DE APPR. DATE 08.09.30

W/O:		,	٧	VORK ORDI	ER CHANG	GES					
DATE	STEP	PRO	PROCEDURE CHANGE By Da					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·							
	-										
Part No		PAR #:									
	R	esolution:							· · · · · · · · · · · · · · · · · · ·	_ Date: _	
NCR:			WORK OR	DER NON-C	ONFORM	ANCE	(NCR	()			-
DATE	STEP	Description of NC		Corrective Action Section			<u> </u>	Verifica	ition	Approval	Approval
		Section A	Initial Chief Eng		Description Chief Eng		Sign & Date	Section	1 C	Chief Eng	QC Inspector
				,		:					
					•						
					X.						
	 										
,											
									:		
		·									
	1							1			•



Dart Aerospace L	Ltd
------------------	-----

Dart Ae	rospace	Ltd								\$ * '
W/O:			W	ORK ORDER CHA	NGES					
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								3	•	
									•	
		,					•		-	*
Part No	:	PAR #:	Fault Cat	egory:	NC	R: Yes	No. DQ	A:	Date: _	<u> </u>
		esolution:								
NCR:		V	ORK ORE	ER NON-CONFOR	RMANCE	(NCF	l)			
DATE	STEP	Description of NC		Corrective Action Section			Verific	cation	Approval	Approval
	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	on	Sign 8 Date		on C	Chief Eng	QC Inspector
									a v	· · · · · ·
					7.jų	Sec.		•		